



TECHNICAL BULLETIN

TEMPORARY USE OF ALTERNATE POWER SUPPLY for the following products : (XTS - V+ - TBS - HWD)

Due to a supplier issue, we are unable to supply the current part number 1052.00001.00 until early January 2019. We are using an alternate part from another supplier that requires the use of an adapter harness and molex connectors. This will have no effect on the reliability of the machine and the connection point will be the same to the existing wiring on the machine.

PARTS AFFECTED:

POWER SUPPLY (ORIGINAL) 1052.00001.00

(REPLACEMENT) KIT: 1000.00119.00

INCLUDES: POWER SUPPLY, HARNESS, 2 PIN ADAPTER AND 3 PIN ADAPTER

